

STORAGE CONDITIONS

- All goods to be kept in its original packaging.
- In general, the goods may not be exposed to direct sunlight, as well as, to a strong electromagnetic field and any unusual mechanical stress. It is recommended to store it in dark conditions and sheltered premises.
- Recommended storage temperature: +10 °C to +30 °C
- Recommended storage humidity: 40 % 60 % RH
- It is advised to process the goods within 12 months of its delivery.